



## AG-3501 DRAWING DESCRIPTION

NO	Q'TY	PART / NO	CIBTEBT / SPEC'
1	1	710801	GUN BLOCK
2	1	710802	GUN BLOCK COVER
3	1	710203	MODULE
4	2	512012	O-RING (AN-012)
5	1	914309	HOT MELT HOSE NIPPLE
6	3	511011	O-RING (P-11)
7	1	710605	AIR PIPE
8	1	710406	GUN CONNECTOR
9	1	710401-3	HEATER 240V 250W
10	1	710405	SENSOR PT 100Ω
11	2	41A06050	WRENCH BOLT (M6X50L)
12	4	411304	SPRING WASHER
13	2	41A06030	WRENCH BOLT (M6X30L)
14	2	461102	BLANK (PS 1/4")
15	1	451202	SET SCREW BOLT (PT 1/8")
16	1	712608	CONNECTOR FIX BOLT
17	1	41G04004	SET SCREW BOLT (M4 x 4L)
18	1	411306	SPRING WASHER
19	1	710803	NUT
20	1	710609	AIR SOL VALVE
21	4	41A05025	WRENCH BOLT (M5X25L)
22	2	41B03008	BOLT (M3X8L)