


5. SAG-3501 DISINTEGRATION AND EXPLAIN



SAG-3501 DRAWING DESCRIPTION

NO	Q'TY	PART / NO	CIBTEBT / SPEC'
1	1	711801	GUN BLOCK
2	1	711802	GUN BLOCK COVER
3	1	710207	SPRAY MODULE SET
4	3	512011	O-RING (AN-011)
5	1	710418	HOT MELT HOSE NIPPLE
6	1	511016	O-RING (P-16)
7	1	51004-2	FILTER (#80)
8	2	710605	AIR PIPE
9	1	710406	WIRE CONNECTING CONNECTOR
10	3	222103	HEATER 220V 300W
11	1	710405	SENSOR PT 100Ω
12	2	41A06050	LENTCH BOLT (M6X50L)
13	4	411304	SPRING WASHER
14	2	710405	LENTCH BOLT (M6X50L)
15	2	710607	SPRING WASHER
16	1	711802	BRACKET
17	1	711803	INSULATING MATERIAL
18	17	41G08010	SET SCREW BOLT (M8X10L)
19	1	710608	WIRE FIXING EQUIPMENT
20	1	41G04004	SET SCREW BOLT (M4X4L)
21	1	411306	SPRING WASHER (M10)
22	1	411506-1	HEXAGON NUT
23	2	710609	AIR SOL VAVLE
24	4	41A05025	LENTCH BOLT (M5X25)
25	4	41C04010	BOLT (M4X10L)
26	1	730500-17	NOZZLE BLOCK
27	1	S3501-L2	SPRAY NOZZLE